

F6 Charnière

Porte démontable

Acier zingué ou acier inoxydable



Technical drawing of a mechanical part, likely a bracket or support, showing dimensions and labels:

- Axe de dégagement**: Label for the axis of clearance, pointing to the curved section on the left.
- E**: Dimension indicating the distance from the right edge to the center of the hole.
- W**: Dimension indicating the width of the part.
- $\varnothing P$** : Dimension indicating the diameter of the hole.
- H**: Dimension indicating the height of the part.
- L**: Dimension indicating the length of the part.
- $\varnothing 3.25$** : Dimension indicating the diameter of the hole.
- TAILLE REELLE**: Label indicating the drawing is at natural scale.

S	Taille	L	E	H	J	P	T	W
	3 - 4	22.2	4	4.0	10	3.2	0.8	13
	7 - 8	34.9	6.4	4.8	13	4.0	1.0	19
	11 - 12	50.8	9.5	6.4	16	4.8	1.3	22
	15 - 16	69.9	12.7	6.4	19	6.4	1.5	25.5

N Acier zingué

S Acier inoxydable

3	22 à gauche
4	22 à droite
7	35 à gauche
8	35 à droite



11 51 à gauche
12 51 à droite
15 70 à gauche
16 70 à droite (représentée)

F6 - 23 - **M** **S** AW




Acier zingué ou acier inoxydable

Voir tableau




Référence		
Orientation	Acier	Acier inoxydable
Droite (représentée)	F6-20-N1A50WR	F6-20-S1A50WR
Gauche	F6-20-N1A50WL	F6-20-S1A50WL



- Acier zingué ou acier inoxydable

Voir tableau



Matériau	Référence
Acier	F6-22-N1-3W1
Acier inoxydable	F6-22-S1-3W1